NovaLCT-Mars Upgrading Instructions

1. Version Route

V4.2.6 ←V4.2.5 ←V4.2.4 ←V4.2.2 ←V4.2.1 ←V4.2.0 ← historical versions

2. Major Contents of Version for Upgrading and Modification

(Compared with Last Version)

V4. 2. 6

Version &	June 26 th , 20	15
release date:		
Contents	Upgrading	Added the upgrade package that supports V900;
updated:	of function	2. Added the resolutions 3840*1080 and 2560*1600 for the Nova3D HD device;
		3. Added the upgrade package that supports Nova3D HD;
	Bug	Rectified the quantity display issue in Device Details on the main
		interface;
	renovation	2. Rectified the reaction failure between the LCT and brightness
		tool in the Russian system and French system;
		3. Rectified the Pro or V900 crash resulting from clicking after it is
		configured with redundancy;
		4. Rectified the failure of the loading system if the configuration file
		does not match the information of the current sending card;
		5. Rectified the brightness adjustment failure if the brightness tool,
		configured with redundancy between the cascading sending
		cards, is powered off;
Writer:	Li Jin	

V4.2.5

Version &	V4.2.5 Apr	il 26 th	1, 2015
release date:			
Contents	Upgrading	1.	Support the following driver chips: MBI5252, 5041B, 5041Q, 5045,
			5043, 5038, 5124, A043 as well as MY9862, 9269, and 9366;
updated:	of function	2.	Support NovaPro device to be named and displayed on LCD display;
		3.	Add 3D function setting;
		4.	Support advanced users to change login password;
		5.	Support cabinet configuration file to be imported to a specified sending
			card;
		6.	Support hardware automatic adjustment of brightness;

		7.	Support Dark or Bright Lines recovery for cabinet;
		8.	Support NovaPro cascading through USB;
		9.	Support offline LCT demo;
		10.	Add screen gradual lighting function;
		11.	Support screen calibration to be saved cabinet by cabinet and
			consecutive saving;
		12.	Support multiple batches to be renamed and batch configuration file to
			be imported/exported;
		13.	Support data group switch to be searched in a smart way;
	Bug	1.	Resolve the fault caused by Windows 8 permission issue;
		2.	Resolve black screen issue that occurs if ambient brightness exceeds
	renovation		60000Lum;
		3.	Resolve the reading fault that occurs if more than 10 pieces of
			redundancy information are added;
		4.	Cancel the limitation on width and height modification made to
			sending card EDID;
		5.	Resolve name incompleteness issue that occurs in expansion mode;
		6.	Resolve OE high level effectiveness setting issue that occurs in general
			chips;
		7.	Resolve the Delete button clicking failure issue;
		8.	Resolve the software restart failure that occurs after the first step is
			completed if the sending card is closed;
		9.	Resolve the Configuration button clicking failure issue that occurs if no
			information is available on the screen;
		10.	Resolve the issue that 10 sending cards are shown on the screen but
			only one sending card is connected actually;
		11.	Resolve the error that occurs during Flash inspection if a vacancy is
			reserved;
Writer:	Li Jin		

V4.2.4

Version &	V4.2.4 Feb	ruary03 th , 2015
release date:		
Contents	Upgrading	1. Support bright and dark line adjustment appeared after the screen
		combined with cabinets, which can quickly adjust bright and dark lines
updated:	of function	between cabinets;
		2. upport upload the results of the bright and dark line adjustment, which
		can directly apply to the adjusted results;
	Bug	1. Added function selection of bright and dark lines Screen Gamma is set
		to 1, after closing restoration;
	renovation	2. Resolve the error that occurs during Flash inspection if a vacancy is
		reserved;

		Fixed Upload be support expansion	C	dark lines	correction	coefficient	does	not
Writer:	Li Jin							

V4.2.2

Version &	V4.2.2 Augu	ust 26 th , 2014
release date:		
Contents updated:	Modification and perfection	 Helping the document save advertising pages in the presence of network; Synchronization of color temperature supporting value and hardware; Problem solving that the positioning is inaccurate through a sending card program package.
Writer:	Li Jin	

V4.2.1

Version	&	V4.2.1 Augu	ıst 15 th , 2014
release date:			
Contents		Modification	1. Multi-batch adjustment: multi-batch uploading coefficients are normal; deletion of multi-batch normal use; the color is kept in accordance with the
updated:		and	selected color when adjusting the brightness; and other known Bug
		perfection	renovation; 2. Testing tools: the Cancel button is clicked and errors are reported at first
			use of positioning background image; normally switch over pages;
			3. Place changing for storage of main program (to solve limits of
			authority); 4. High-byte low-bit BUG of RefNumPerVs of receiving card new
			parameter;
			5. Help document has advertising pages in the presence of network;6. Calibration function to obtain receiving card documents is in accordance
			with the method for saving documents of the receiving card in display configuration;
			7. Configuration after successful reading of the receiving card is acquired
			through copy approach, to solve new display upon next opening;
			8. Upgrading of hardware sending card program package.
Writer:		Li Jin	

V4.2.0

Version	&	V4.2.0	June 13 th , 2014
release date:			

	Upgrading	1.	Multi-batch calibration and adjustment of public color gamut;
	170	2.	Flash configuration function of lamp plate;
Contents	of function	3.	Color temperature simple-adjustment pull rod increased;
updated:		4.	Programmed control brightness, wherein an automatic brightness
ap dated.			adjustment interface increases current brightness value;
		5.	User-defined Gamma table saved in receiving card configuration
			document;
		6.	Positioning function of testing tool: background color refillable pictures increased;
		7.	Functions of import and export of all configuration documents in
			NovaLCT increased;
		8.	Newly increased setting of coordinates for starting of main program;
		9.	Calibration coefficient reset according to size of the lamp plate or
			pixel points;
		10.	Inspection of Flash checker newly increased;
		11.	Reading and writing of special shaped cabinet configuration software
			newly increased;
		12.	Reading and writing of cabinet ID newly increased;
		13.	Newly increased supporting to 9868, 2028 chips;
		14.	Online calibration to support verification of Flash calibration
			coefficient of the lamp plate;
		15.	Setting of display screen, wherein the on-load amount of the internet
			access exceeds the hint (size:1G, effective rate: 95%);
		16.	Gradual brightness adjustment through a brightness tool (timed and
			automatic brightness adjustment);
		17.	Initialized setting of current gains;
		18.	Installation package supports starting of registration of Windows8
			brightness tool upon starting up;
	Modification	1.	Partial register open of 5045, 5042B and 5124 chips supported;
		2.	Selection according to pixel domain, which improves the condition
	and		that a red box hint is increased when exceeding the domain;
	perfection	3.	Application of returning domain increased at the selected area;
		4.	Flash operation and viewing of the lamp plate, with saving function
			automatically opening chroma calibration;
		5.	Optimization of function use of testing tool;
		6.	E-mail configuration support: SSL safe mode;
		7.	Setting of register initial value of 16136 chip;
	Bug	1.	Bug renovation of color rendition, and drawing of user-defined
			Gamma curve;
	renovation	2.	Problem of Chinese displayed in main interface;
		3.	Modification of error appeared in reading DVI refresh rate of a second
			card during monitoring;
		4.	$Modification \ of \ Nova. Windows. Forms. Custom Message Box. dll; \ and$
			modification of incomplete language display.

ter: Li

3. Compatibility Instructions

Incompatible with customized Version